



Architectural

General Interior Appearance
 Wall finishes, ceiling finishes, & floor finishes are worn
 Well maintained



Architectural

(<u>7</u>)

𝔅 Building Code

- Triggers based on amount of work done
 Large classrooms need 2 means of
- egress

 Guardrail heights at cafeteria stairs are noncompliant
- Elevators do not fit emergency stretcher
- Have operational issues
- ADA compliance doors, stairs, etc. • Hardware – fair to poor condition





(<u>7</u>)

Architectural


- Building Exterior Envelope (Continued)
 - Brick & ornamental concrete deterioration & cracks creates safety hazard (RFP being finalized)
 - Original main entrance water infiltration, deterioration & cracks, safety Options
 - Minor façade / roof leaks
 - · Lower-level infiltration at Principal's Office



Structural

Main Building

- Structural sub-floor deterioration
 - Floor finish rough & wavey, vibrates
 Continues to be funded on an annual or biannual basis to address issues on a piecemeal basis
- Max floor loading 125 PSF
- Otherwise structurally sound



Electrical

- b Building Power
- Great condition
- Ample power source available; limited power distribution (i.e. outlets)
- Life Safety
 - Some classes & corridors missing emergency powered lights
 - Recommend adding carbon monoxide detectors in classrooms & Children's Castle



Electrical

Interior Lighting
 Has continually been upgraded
 95% is LED



Electrical

- (h) Telephone System Needs Updating
- ℅ Speaker / Paging System Needs Updating
- ℎ Info Tech (IT)
 - Good operating condition
 - Wi-Fi throughout school
 - Newline Panels in classrooms
 - Cafetorium only a portable presentation system

(7)

℅ Site Lighting

Electrical

- Insufficient general parking lighting
 Some egress doors missing emergency lighting
- Traffic patterns are currently under evaluation under a separate study which may affect site lighting



HVAC

- Heating System
 - In general, heating is sufficient & in functional condition
 - Boilers: 1/3 of life expectancy used
 - Admin separate HVAC system not functioning - scheduled for replacement
- Limited Cooling Throughout
 - Some window A/C units throughout
 - No central air conditioning
 - No exterior wall insulation, other than in Gym
- Children's Castle: ventilation by windows only



Plumbing

- Insufficient Water Pressure
 Need booster pump
 - Fixtures on upper levels have insufficient water pressure
- Water Heaters Near End of Useful Life
- Pump issue Children's Castle water temperature is low
- Drinking fountains and supply piping should be addressed
- Other Fixtures Fair to Good Condition



(₇)

(Z)

Fire Protection

- Fire Pump
 - · Shows wear and tear
 - · Fire-rated room enclosure does not meet new Building Code standards · Possible unstable water pressure

 - Requires further investigation
- Standpipes Not Located in Children's Castle
 - Not up to current design practices



Fire Protection


Sprinkler System

• System requires an inspection to determine adequate operation / flow • Attic

- Heads need cleaning & inspection Loaded with insulation
- o One dislodged
- Ceiling


• Heads need cleaning & inspection Sagging ceiling obstructs sprinkler heads Sprinklers missing at oil tank canopy

• Suppression system missing at





(7)






Disposition Scenarios - DRAFT

No.	Disposition	Estimated Years of Service
Α.	Maintain Existing Facility with Minor Reno*1	20 YRS
В.	Renovate to Improve (Major & Minor Reno)	20 – 30 YRS
C.	Dispose/Sell Existing Facility*2	N/A
D.	Demo Main Building, Construct Addition for Classrooms for 450 Students*3	30 – 40 YRS
E.	Demo All Buildings, Construct New School on Site for 450 Students*3	40 – 50 YRS
F.	Construct New School on Different Site*4 (Demo, Repurpose, or Sale of Existing Building)	40 – 50 YRS

progents Requires swing space for students and/or phased construction. Aequires another site. Cost of acquisition of new site not included. Assumes 2023 construction costs. This is based on a preliminary conceptual estim from the Town on scenario parameters. ing feedback



SCENARIO B


Minor Impro


Major Impro

New Buildi

Renovate to Improve







Disposition Scenarios - DRAFT

No.	Disposition	Estimated Years of Service			
Α.	Maintain Existing Facility with Minor Reno*1	20 YRS			
В.	Renovate to Improve (Major & Minor Reno)	20 – 30 YRS			
C.	Dispose/Sell Existing Facility*2	N/A			
D.	Demo Main Building, Construct Addition for Classrooms for 450 Students*3	30 – 40 YRS			
E.	Demo All Buildings, Construct New School on Site for 450 Students*3	40 – 50 YRS			
F.	Construct New School on Different Site*4 (Demo, Repurpose, or Sale of Existing Building)	40 – 50 YRS			
*1 – Assume approximately \$250 - \$500K in yearly cost for upkeep and periodic required improvements. Requires review. *2 – Assumes educational program is addressed in other existing buildings. Refer to Scenario F for a new school to house encourse.					

- *3 Requires swing space for students and/or phased construction.
 *4 Requires another site. Cost of acquisition of new site not included.
 *5 Assumes 2023 construction costs. This is based on a preliminary conceptual estimate that in from the Town on scenario parameters.

Disposition Scenarios - DRAFT

No.	Disposition	Estimated Years of Service	Project Cost (\$)*5			
Α.	Maintain Existing Facility with Minor Reno*1	20 YRS	\$5-10M			
В.	Renovate to Improve (Major & Minor Reno)	20 – 30 YRS	\$35-40M			
C.	Dispose/Sell Existing Facility*2	N/A	\$0 or credit			
D.	Demo Main Building, Construct Addition for Classrooms for 450 Students*3	30 – 40 YRS	\$51-61M			
E.	Demo All Buildings, Construct New School on Site for 450 Students*3	40 – 50 YRS	\$66-79M			
F.	Construct New School on Different Site*4 (Demo, Repurpose, or Sale of Existing Building)	40 – 50 YRS	\$64-77M			
*2 – As pi	*1 – Assume approximately \$250 - \$500K in yearly cost for upkeep and periodic required improvements. Requires review. *2 – Assumes educational program is addressed in other existing buildings. Refer to Scenario F for a new school to house educational program. 3 – Requires swine space for students and/or phased construction.					

(₇)

nent following feedback

- other site. Cost of acquisition of new site not included
- es 2023 construction costs. This is based on a preliminary conceptual esti from the Town on scenario para



(7)

t following feedback

CONTACT US



Gienapp Architects Dale Gienapp, AIA, MCPPO 20 Conant Street, Danvers, MA 01923

978-750-9062 978-750-9063 (fax)

dgienapp@GienappArchitects.com

🕨 YouTube 🖪 🞯 in